

Plan to Improve Corridors and Neighborhood Connections in Baldwin Park


Errata Sheet


Updated February 28, 2011

This document describes the errata for *Plan to Improve Corridors and Neighborhood Connections in Baldwin Park: A Report to the City of Baldwin Park*, printed November, 2010.

Appropriate corrections have already been made in the downloadable version of the report posted at http://www.lgc.org/reports/baldwin_park/.

Corrections

Page	Location	Change	
14	Drawing for 1.2. Baldwin Park Boulevard north of Los Angeles Street	The base aerial view used in the drawing was based on an incorrect location. It was redrawn based on the correct base aerial view.	 An aerial photograph showing the intersection of Baldwin Park Blvd and Los Angeles St. The drawing overlays the photograph with proposed improvements, including a red double-line corridor along Baldwin Park Blvd, green circular markers representing trees, and a yellow highlighted area at the intersection. The text 'Baldwin Park Blvd.' and 'Los Angeles St.' are visible on the image.

Page	Location	Change	
16	Drawing for 1.3. <i>South of Los Angeles Street to Ramona Boulevard</i>	The base aerial view used in the drawing was based on an incorrect location and showed a road diet with only one travel lane in each direction. It was redrawn based on the correct base aerial view and correctly showing two travel-lanes in each direction.	
20	Drawing for 2.1. <i>Maine Avenue north of Los Angeles Street</i>	The base aerial view used in the drawing was based on an incorrect location and showed two travel-lanes in each direction. It was redrawn based on the correct base aerial view and correctly showing a road diet with one travel lane in each direction.	